FEED BIG BERTHA
Audit and Test Mode
ONLY for games with a Multi Color Dot Matrix Display

To enter the AUDIT mode, press SW3 on the CPU. The display will read 00 AUD.

The Audit # will be displayed on the LEFT and the Audit information on the RIGHT.

1. Press SW3 again to display the **Number of Coins** inserted.
The right side will display the low three digits.
Press and hold SW2 to display the high three digits.

2. Press SW3 again to display the **Number of Tickets Dispensed**.
The right side will display the low three digits.
Press and hold SW2 to display the high three digits.

3. Press SW3 again to display the **Number of Games Played**.
The right side will display the low three digits.
Press and hold SW2 to display the high three digits.

4. Press SW3 again to display the **High Score**.
The right side will display the low three digits.
Press and hold SW2 to display the high three digits.

5. Press SW3 again to display the **Last Game Score**.
The right side will display the low three digits.
Press and hold SW2 to display the high three digits.

6. Press SW3 again to display the **Maximum Ticket Setting** mode.
The right side will read **MAX** and the left side will display the chosen
maximum ticket setting.

Press the **START** button to select the following ticket settings:

0 = NO tickets during the game
1 = Maximum of 1 ticket during game
2 = Maximum of 2 tickets during game